

# URS

#### Washington Division

July 31, 2008

Nuclear Materials Licensing Section DMS/NMSB-B U.S. Nuclear Regulatory Commission, Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011-8064

Attention:

Jackie Cook

Subject:

AMMENDMENT FOR NRC MATERIAL LICENSE NO. 03-27724-01

NRC Docket No. 030-35960 DA Contract DAAA09-97-C-0098

Dear Ms. Cook:

Washington Demilitarization Company is submitting the enclosed Amendment for Material License 03-27724-01 (Docket No. 030-35960). Enclosed are copies of affected pages from the Pine Bluff Chemical Disposal Facility (PBCDF) radiation program and prospective review. Change being made will be to suspend required use of personal radiation dosimetry based on the data presented in this letter.

Should you have any questions please contact me at 870-540-2183.

Sincerely,

Michell Coats, MS, ClH, CSP, CHMM

Safety Supervisor Radiation Safety Officer

MC/mc Enclosures

CC:

PMCSD – Mark Greer

PMCSD – Clara Moraga PBA RSO – Rick Sabin

WDC VP Project General Manager - Mr. David Reber

WDC Plant Manager - Mr. Guy Campbell

WDC Contracts - Mr. Greg Hayley

WDC Safety - Mr. Marty Buell

P.O. Box 20130 • Pine Bluff, AR 71612 • Phone: (870) 540-2190 • Fax: (870) 540-2189

870 540 2206 SAFETY FAX 03:31:48 p.m. 07-31-2008 2 /3

Amendment for NRC License No. 03-27724-01

### PROSPECTIVE REVIEW TO SUPPORT AMMENDMENT

In accordance with the site Radiation Safety Program, monitoring of personal exposure has been accomplished from the time the fixed gauges were installed at PBCDF in April of 2003 through January of 2006. Sufficient documentation has been acquired to demonstrate personal exposure monitoring (i.e. dosimetry) is no longer required.

## **Landauer Luxel Badge Results**

Monitoring Period	High TEDE Reported (in REM)	Avg. TEDE Reported (in REM)
04/15/03 - 01/14/04	0.007	0.003
01/15/04 01/14/05	0.009	0.003
01/15/05 – 01/14/06	0.001	0.00025 *

<sup>\*</sup> Facility became operational during 2005, thus less frequent access to the gauges and lower personal exposure was experienced. Six of the eight users were ND.

#### Conclusion:

Based on the data reported above the highest TEDE (whole body) reported was 0.009 rem per year, therefore, personal exposures are expected to be significantly less than 10% of the threshold established in 10 CFR 20.1201 of 5 rem per year for TEDE whole body (i.e. 500 mrem/year).

3/3

PB-IH-010 Radiation Safety Program

REV 4 19 Nov 07 CHG 1 23 Jan 08

- 6.3.4 All applicable safety and maintenance procedures including (but not limited to) PB-IH-016, DFS Jam Sensor Lockout/Tagout Leak Test and Shutter Check, will be followed when working with the gauges.
- 6.3.5 No restricted areas (radiation areas) are anticipated because of the nature of the equipment and installation; however, the RSO or Alternate shall determine, during gauge surveys, if restricted areas are present. If restricted areas are found during the survey, the proper signage shall be posted. Personnel working in the identified radiation areas shall receive training equivalent to that listed in step 6.2.1.2.

#### 6.4 INSPECTIONS, SURVEYS, AND WIPE TESTS OF THE JAM SENSORS

- 6.4.1 The Ohmart gauges shall be tested for leakage (wipe test) every 3 years as required by the NRC. Any source that is received without a certificate indicating the equipment has been leak tested within the six months of transfer shall not be put into service until the source is leak tested.
- 6.4.2 Any gauge in storage and not being used need not be tested. When the gauge is removed from storage for use or transfer, it shall be tested prior to use or transfer.
- 6.4.3 Wipe tests shall be collected by the RSO or designee in accordance with PB-IH-016. The samples shall be analyzed by a lab that is licensed and certified by the NRC or Agreement State with the detection capability specified by the NRC. Detected leaks shall be reported to the NRC within five days of the test results. The report shall specify the source involved, test results, and corrective actions taken. Immediate action will be taken by WDC to ensure the leak is contained to minimize employee exposure. Results of the leak test results shall be kept in microcuries and shall be maintained for inspection by the NRC.
- 6.4.4 Each gauge shall be tested for proper operation of the ON-OFF shutter mechanism and indicator at six-month intervals. This test shall be conducted in accordance with PB-IH-016, DFS Jam Sensor Lockout/Tagout Leak Test and Shutter Check.
- 6.4.5 The RSO or designee shall conduct a physical inventory of all devices every six months. Inventory records shall be maintained for a minimum of three years from the date of the inventory. The record shall include the quantity and type, manufacturers name and model number, number of devices, and date of the inventory.

#### 6.5 PERSONAL MONITORING/DOSIMETRY

- 6.5.1 Personnel involved in installation, relocation, removal, maintenance, radiation surveying, leak testing, or shipping of the Jam Sensors will be provided, and required to use, personal TLDs (or other approved dosimetry devices). The dosimetry devices shall be exchanged on a quarterly basis during the above operation.
- 6.5.2 The personal monitoring program will be evaluated after two years to determine if personal monitoring should continue.

#### 6.6 RADIATION DETECTION EQUIPMENT

- 6.6.1 There shall be at least two survey meters on-site. shall be operable and the calibration shall be curre capable of measuring at least 1 through 200 millire calibrated to measure the appropriate radiation so
- 6.6.2 The survey meters will be returned to the manufaction annual basis. The calibration dates will be stagge meter will be available at all times.

has been conducted and sufficient documentation has been acquired to demonstrate that personal exposure monitoring is no longer required for routine operations such as shutter checks, radiation surveying, leak testing, or preventative maintenance checks/calibrations..

Page 4

# ACCEPTANCE REVIEW MEMO (ARM) Washington Demilitarization Co. License No.: 03-27724-

Licensee:	vvasnington Demilitarization Co.	License No.: 03-27/24-01		
Docket No.:	030-35960	Mail Control No.: 471893		
Type of Actio	on: Amend	Date of Requested Action: 07-31-08		
Reviewer Assigned:		ARM reviewer(s): J. Cook		
Response	Deficiencies Noted During Acceptance Review			
	<ul> <li>[ ] Open ended possession limits. Submit inventory. Limit possession.</li> <li>[ ] Submit copies of latest leak test results.</li> <li>[ ] Add IC L.C./Fingerprint LC, add SUNSI markings to license.</li> <li>[ ] Confirm with licensee if they have NARM material.</li> </ul>			
Reviewer's Initials: Date:				
□Yes □No	Request for unrestricted release	Group 2 or >. Consult with Bravo Branch.		
□Yes □No	Yes □No Termination request < 90 days from date of expiration			
□Yes □No	Yes No Expedite (medical emergency, no RSO, location of use/storage not on license, RAM in possession not on license, other)			
□Yes □No TAR needed to complete action.				
Branch Chief's and/or HP's Initials: Date:				
SUNSI Screening according to RIS 2005-31				
□Yes ☑No	<del>-</del>	<b>illable</b> if <u>any</u> item below is checked		
General guid				
RAM = or > than Category 3 (Table 1, RIS 2005-31), use Unity RuleExact location of RAM [suite #, bldg. #, location different from mailing address]				
(whether = or > than Category 3 or not)				
Design of structure and/or equipment (site specific)				
Information on nearby facilitiesDetailed design drawings and/or performance information				
Emergency planning and/or fire protection systems				
Specific guidance for medical, industrial and academic (above Category 3): RAM guantities and inventory				
Manufacturer's name and model number of sealed sources & devices				
Site drawings with exact location of RAM, description of facility				
RAM security program information (locks, alarms, etc.)Record Plan specifics (routes to/from RAM, response to security events)				
Vulnerability/security assessment/accident-safety analysis/risk assess				
Mailing lists related to security response				
Branch Chief's and/or HP's Initials: Date: _AUG 2 2 2008				

This is to acknowledge the receipt of your letter/application dated

7.31.08
, and to inform you that the initial processing,
which includes an administrative review, has been performed.

There were no administrative omissions. Your application will be assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card:

The action you requested is normally processed within 90 days.

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 47/893
When calling to inquire about this action, please refer to this mail control number. You may call me at 817-860-8103.

Sincerely,

January Alexander

DATE

DATE

1.21.08

DATE

1.22.17

DATE

1.23.17

DATE

DATE

DATE

1.23.17

DATE

DATE

1.23.17

DATE

DATE

1.23.17

DATE

1.23.17

DATE

DATE

1.23.17

DATE

DATE

1.23.17

DATE

DATE

DATE

1.23.17

DATE

DATE

1.23.17

DATE

DATE

DATE

1.23.17

DATE

D

NRC FORM 532 (RIV) (10-2006)

Licensing Assistant

		: (FOR LFMS USE) : INFORMATION FROM LTS	
BET	WEEN:	:	
License Fee Management Branch, ARM		: : Program Code: 03120 : Status Code: 0	
Reg	ional Licensing Sections	: Fee Category: 3P : Exp. Date: 20120531 : Fee Comments: : Decom Fin Assur Reqd: N	
LIC	ENSE FEE TRANSMITTAL		
Α.	REGION		
1.	APPLICATION ATTACHED Applicant/Licensee: WASHINGTON DEMILITARIZATION CO. Received Date: 20080731 Docket No: 3035960 Control No.: 471893 License No.: 03-27724-01 Action Type: Amendment		
2.	FEE ATTACHED Amount: Check No.:		
3.	COMMENTS Signed Date	Collien Murnahan	
В.	LICENSE FEE MANAGEMENT BRANCH (Checl	k when milestone 03 is entered //)	
1.	Fee Category and Amount:		
2.	Correct Fee Paid. Application may be processed for: Amendment Renewal License		
3.	OTHER		
	Signed Date	<del></del>	